



E510 Specifications

Last Updated : 04-Jul-2012

Issue Number : 6200139100

General Specifications	
Printing resolution (dpi)	4800* (horizontal) X 1200 (vertical) * Ink droplets can be placed with a pitch of 1/4800 inch at minimum.
Interface	USB Port: Hi-Speed USB *1 *1 A computer that complies with Hi-Speed USB standard is required. Since the Hi-Speed USB interface is fully upwardly compatible with USB 1.1, it can be used at USB 1.1.
Print width	8 inches/203.2 mm (for Borderless Printing: 8.5 inches/216 mm)
Operating environment	Temperature: 5 to 35 °C (41 to 95 °F) Humidity: 10 to 90 % RH (no condensation)
Storage environment	Temperature: 0 to 40 °C (32 to 104 °F) Humidity: 5 to 95 % RH (no condensation)
Power supply	AC 100-240 V, 50/60 Hz
Power consumption	Printing (Copy): Approx. 12 W Standby (minimum): Approx. 0.6 W *1*2 OFF: Approx. 0.3 W *1 *1 USB connection to PC *2 The wait time for standby cannot be changed.
External dimensions	Approx. 17.7 (W) X 12 (D) X 6 (H) inches Approx. 449 (W) X 304 (D) X 152 (H) mm * With the Front Cover retracted.
Weight	Approx. 5.3 kg (Approx. 11.7 lb) * With the FINE Cartridges installed.
Canon FINE Cartridge	Total 1792 nozzles (BK 640 nozzles, C/M/Y each 384 nozzles)

Multiple copy	1- 9, 20 pages
Reduction/Enlargement	Fit-to-page

Scan Specifications	
Scanner driver	TWAIN/WIA (for Windows 7/Windows Vista/Windows XP)
Maximum scanning size	A4/Letter, 8.5" X 11.7"/216 X 297 mm
Scanning resolution	Optical resolution (horizontal X vertical) max: 1200 X 2400 dpi Interpolated resolution max: 19200 X 19200 dpi
Gradation (Input/Output)	Gray: 16 bit/8 bit Color: 48 bit/24 bit (RGB each 16 bit/8 bit)

Was this helpful?

YES. It solved my issue

It covered my problem, but the solution still didn't work

The information on the page is hard to understand

It has nothing to do with my issue

Submit